2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
	Manual					
Angio Americ	an Managed Operations					
19	Angio American/ Metallurgical Coal	Anglo Coal (Moranbah North Management) Pty Limited	Coal Aus	Moranbah North Coal Pty Ltd Moranbah North Coal (No 2) Pty Ltd Mitsui Moranbah North Investment Pty Ltd JFEMA Moranbah North Pty Ltd NS Moranbah North Pty Ltd NS Coal (Moranbah North) Pty Ltd NS Moranbah North Pty Ltd Shinsho Moranbah Coal Pty Ltd	Australia	Moranbah North

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership	4. Status	operation	6. Is the Dam currently operated or closed as per currently approved design?
Moranbah North Mine - Codisposal Area / CDA	21.872 S, 147.948 E	Operated by Anglo American for JV partners	Active	first construction 1998	Yes

7	•	•	Storage Impoundment Volume (m³)	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	complete relevant	categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	its history, failed to be confirmed o certified as stable, or experienced notable stability concerns, as	16. Do you have internal/in house rengineering specialist oversight of this facility? Or do you have external engineering support for this purpose?	
l	Jpstream	34	15,500	33,455	2018	Yes, and a preliminary rehabilitation-closure plan is available.	Nignificant / High	Queensland - Dept. of Env & Science/ Anglo American Technical Standard (AA TS 602 001)	Yes - See Q20 for additional information	Both	Yes, 2019

		20. Any other relevant information and supporting documentation.
place for this dam, and b) does		1
•	• •	Please state if you have omitted any other exposure to tailings facilities through any joint ventures you may have.
•	of more regular extreme	1
	weather events as a result of	1
	climate change, e.g. over the	1
	next two years?	
Yes - See Q20 for additional information	Yes.	Note: Annual Inspections for this facility are carried out by EoR each year. Q12: At present, the rehab-closure plan for the codisposal area, is outlined in the document "201009 Grosvenor EIS Co-Disposal Landform Area Assessment". Q15: The erosion damage at the toe of the decant pipes incident happened in Oct2018. A full investigation and the consequent remedial works, as well as the monitoring measures have been put in place since. Q17: Basic consequence category assessment completed in 2017. The detailed dambreak modelling, including the numerical modelling is being carried out at the present time as part of the proposed upgrade of the CDA. Q18: A detailed rehab-closure plan for the upgraded facility will be within the CDA's Life Of Mine study report being finalised by late 2019, by external consultants. Further it will also include th long term monitoring arrangements for the CDA. Q19: Plan in place in line with Anglo American's Long-term Sustainable Mining Plan. Current upgrading studies uses the flood modelling methodology, with the most recent precipitation data.