2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
		1	!	1		
		1	'		1	
		1	'		1	
		1	!	1		
Anglo Americ	can Managed Operations					
4	Angio American	De Beers Group of Companies	De Beers	De Beers	Canada	Victor
4	Angio American	· ·	De Beers	De Beers	Canada	

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Victor Coarse PK & Low Grade Ore Stockpile	Lat 52°48′38.09″ N Long 83°54′22.82″ W	Owned and Operated	Active	2008	Yes

7. Raising method		Storage Impoundment Volume (m³)	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	complete relevant	categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	its history, failed to be confirmed o certified as stable, or experienced notable stability concerns, as	external engineering support for this purpose?	•
Dry stack	12	5.94M	5.94M	2018	Yes	Minor	Anglo American Technical Standard (AA TS 602 001)	No	Both	Yes, 2004

place for this dam, and b) does to it include long term for monitoring? o	to assess your tailings	
Yes, Yes	res, See Q20 for more	Q17: Done as part of the original environmental impact studies prior to mining. Q19: 2018/2019 Closure design done externally. Report states 1:1000 year return periods AND Extreme Value 1 (EV1) frequency distribution from Environment Canada. Plan in place in line with Anglo American's Long-term Sustainable Mining Plan