2. Specific questions:

	No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
ľ	Anglo America	an Managed Operations					
	13	Anglo American	De Beers Group of Companies	De Beers	De Beers Consolidated Mines and Ponahalo	South Africa	Namaqualand

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Namaqualand Bulk Sample Plant FRD	Lat 29° 35' 22.65" S Long 17° 02' 03.08" E	Owned and operated	Inactive, see Q20 for more information	1975	No, see Q20 for more information

•	• , ,	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	complete relevant	13. What is your hazard categorisation of this facility, based on consequence of failure?	classification system?	its history, failed to be confirmed or certified as stable, or experienced notable stability concerns, as	external engineering support for this purpose?	
Other, See Q20 for more information	N/A	No Information Contained in natural depression	No Information Contained in natural depression	2013	No, see Q20 for more information	Minor	Anglo American Technical Standard (AA TS 602 001)	No	Internal engineering specialist	Yes, See Q20 for more information

place for this dam, and b) does it include long term monitoring?	to assess your tailings	
Yes, Yes	Yes, See Q20 for more information	Q6: The facility is dormant/care & maintenance Q7. Natural Depression similar in risk context to an In-Pit storage, no outer wall Q12: Some documents are available Q17: Natural depression, failure not possible Q19: Plan in place in line with Anglo American's Long-term Sustainable Mining Plan.