2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Anglo Americ	an Managed Operations					
15	Angio American	De Beers Group of Companies	De Beers	De Beers Consolidated Mines and Ponahalo	South Africa	Namaqualand

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Namaqualand Tweepad FRD	Lat 29° 27' 22.14" S Long 17°00' 05.19" E	Owned and operated	Inactive, see Q20 for more information	1980	No, see Q20 for more information

7. Raising method	•	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	•	13. What is your hazard categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	its history, failed to be confirmed o certified as stable, or experienced notable stability concerns, as	external engineering support for this purpose?	•
Downstream	8.5	23M	23M	2013	No, see Q20 for more information	Moderate	Anglo American Technical Standard (AA TS 602 001)	Yes, see Q20 for more information	Internal engineering specialist	Yes, See Q20 for more information

place for this dam, and b) does it include long term monitoring?	to assess your tailings	
Yes, Yes	Yes, See Q20 for more information	Q6: the facility is dormant/care & maintenance Q12: Only some of the design documents are available. Q15: Substantial seepage occurred at the toe. Seepage decreasing through high evaporation and infiltration. Q17: Safety classification was determined as per SANS 10286 in 2004. Environmental impact assessment to follow to include catastrophic failure impact. Q19: Plan in place in line with Anglo American's Long-term Sustainable Mining Plan.